

Tuesday 11AUG09: Ft. Lauderdale Beach Shoreline Assessment

On Tuesday a PI team conducted a shoreline assessment of the Ft. Lauderdale beach after receiving reports of tar balls in the area. The above area was surveyed. The team discovered that the tar balls were spaced out approx. every 20 to 50 ft. They were in groups of 5 to 10 and were observed throughout the entire span of the beach. The size of the tar balls ranged from a dime size to a silver dollar.