

**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Containment Boom Section 2: Collection of Crude Oil and Debris



Preparation of Containment Boom for Deployment in Bayou Lafourche



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Drainage Canal/Bayou Lafourche Intersection: Skimming Operations



Bayou Lafourche Containment Boom Operations



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Containment Boom Deployed on South Side of Bayou Lafourche near Containment Boom Section 2



Crude Oil and Debris Removal near Containment Boom Section 2



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Crude Oil that Surfaced Overnight within the Secondary Containment Berm Housing  
Crude Oil Storage Tank #9195



Washing Operations within the Secondary Containment Berm Housing Crude Oil  
Storage Tank #9195



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Skimming Operations within the Secondary Containment Berm Housing Crude Oil Storage Tank #9195



Debris and Absorbent Material Removed from Bayou Lafourche



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

Bayou Lafourche – North Embankment: Containment & Absorbent Boom Operations



Containment Boom Section 3: Saturated Absorbent Boom Ready for Removal



**Central Crude, Inc.  
Valentine Facility  
Incident Date: February 22, 2007  
Lafourche Parish, Louisiana  
February 25, 2007**

South Embankment of Bayou Lafourche: Containment Boom Operations



Containment Boom Operations within the Secondary Containment Berm Housing Crude Oil Storage Tank #9195

